

Date : 06/25/2025
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 06/25/2025 14:00
Onsite Hours : 00:15

ASEC Report ID : 82554
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : Sunny
Departure Time : 06/25/2025 14:15
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site for a site visit. The technician observed the equipment parked in the front area blocking the entrance to site. There appeared to be grass placed on the dam around pond #1. No contractors were present at this time. No testing was performed at this time.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.