

Date : 02/25/2026
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 02/25/2026 08:00
Onsite Hours : 9:30

ASEC Report ID : 90662
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : cloudy
Departure Time : 02/25/2026 17:30
ASEC Technician Name : Samara Simha Reddy Kandi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Crew continued earthwork operations for Lots #50, 51, and 52. Fill was placed in lifts approximately 6 to 8 inches in loose thickness. The material was spread and graded using a crawler bulldozer. Each lift was compacted using a sheep-foot roller.

Crew also performed similar operations at Lots #39 and 40. Fill material was placed in lifts, spread uniformly with a crawler bulldozer, and compacted using a sheep-foot roller.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Spreading material using crawler bulldozer



Density tests using Nuclear gauge

Date : 02/25/2026
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 02/25/2026 08:00
Onsite Hours : 9:30

ASEC Report ID : 90662
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : cloudy
Departure Time : 02/25/2026 17:30
ASEC Technician Name : Samara Simha Reddy Kandi



Density tests using Nuclear gauge



Density tests using Nuclear gauge



Compacting using sheep foot roller



Spreading material using crawler bulldozer

Date : 02/25/2026
Project No : 2025C149
Client Company : Davidson Homes
Arrival Time : 02/25/2026 08:00
Onsite Hours : 9:30

ASEC Report ID : 90662
Name of the Project : Grove at E. Thompson Mill Rd
Project Location : Buford
Weather : cloudy
Departure Time : 02/25/2026 17:30
ASEC Technician Name : Samara Simha Reddy Kandi



Density tests using Nuclear gauge



Density tests using Nuclear gauge



Compacting using sheep foot roller

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.