

Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Work has continued behind Lots #227 and #228. The contractor has made progress in the preparation of the retaining wall foundation.

Excavation was carried out using a Kobelco SK210H. The geo-grid has been installed across the excavated area, providing reinforcement for the subsequent stages of the retaining wall construction. On top of the geo-grid, a fiber sheet has been applied. Additionally, a granular base of stone has been placed on top of the fiber sheet preparing the area for the next phases of construction.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

ASEC Report ID : 79526
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/02/2025 17:00
ASEC Technician Name : Vamsi Polisetty



Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

ASEC Report ID : 79526
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/02/2025 17:00
ASEC Technician Name : Vamsi Polisetty



Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

ASEC Report ID : 79526
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/02/2025 17:00
ASEC Technician Name : Vamsi Polisetty



Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

ASEC Report ID : 79526
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/02/2025 17:00
ASEC Technician Name : Vamsi Polisetty



Date : 04/02/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/02/2025 08:00
Onsite Hours : 9:00

ASEC Report ID : 79526
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/02/2025 17:00
ASEC Technician Name : Vamsi Polisetty



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.