

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Work has continued behind Lots #225-230. The contractor has made progress in the preparation of the retaining wall foundation.


The construction of the retaining wall has commenced, with the first course of the wall successfully laid using DMDPro Strilface Gray blocks along Lots #225-230. The alignment, setting, and securing of the initial layer have been completed. Beneath the first layer of the retaining wall, a compacted base of No. #57 stone has been placed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



ASEC Report ID : 79596
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/04/2025 16:00
ASEC Technician Name : Vamsi Polisetty

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00



ASEC Report ID : 79596
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/04/2025 16:00
ASEC Technician Name : Vamsi Polisetty

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00



ASEC Report ID : 79596
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/04/2025 16:00
ASEC Technician Name : Vamsi Polisetty

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00



ASEC Report ID : 79596
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/04/2025 16:00
ASEC Technician Name : Vamsi Polisetty

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00



ASEC Report ID : 79596
Name of the Project : Riverwood Retaining Wall
Project Location : Dallas
Weather : sunny
Departure Time : 04/04/2025 16:00
ASEC Technician Name : Vamsi Polisetty

Date : 04/04/2025
Project No : 2025C150
Client Company : Davidson Homes
Arrival Time : 04/04/2025 08:00
Onsite Hours : 08:00



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.