

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Work has continued behind Lots #224-#229. The contractor has made progress in the preparation of the retaining wall foundation and the Lots #224-#229.

Due to saturation from the previous day's rainfall, the job site remained wet, impacting ongoing activities. Material delivery from the supplier continued throughout the day. To prepare for the next day's production, the contractor initiated aeration of wet soils within Lots #224 to #229. Equipment utilized included a Kobelco 310LC excavator, along with Bobcat 265 and Takeuchi TL12R2 compact track loaders. By midday, the contractor focused efforts on completing the drying process.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you



ASEC Report ID : 81295  
Name of the Project : Riverwood Retaining Wall  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 05/01/2025 14:00  
ASEC Technician Name : Vamsi Polisetty

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



ASEC Report ID : 81295  
Name of the Project : Riverwood Retaining Wall  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 05/01/2025 14:00  
ASEC Technician Name : Vamsi Polisetty

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



ASEC Report ID : 81295  
Name of the Project : Riverwood Retaining Wall  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 05/01/2025 14:00  
ASEC Technician Name : Vamsi Polisetty

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



ASEC Report ID : 81295  
Name of the Project : Riverwood Retaining Wall  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 05/01/2025 14:00  
ASEC Technician Name : Vamsi Polisetty

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



ASEC Report ID : 81295  
Name of the Project : Riverwood Retaining Wall  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 05/01/2025 14:00  
ASEC Technician Name : Vamsi Polisetty

Date : 05/01/2025  
Project No : 2025C150  
Client Company : Davidson Homes  
Arrival Time : 05/01/2025 08:00  
Onsite Hours : 06:00



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.