

Date : 06/05/2025  
Project No : 2025C160  
Client Company : Artisan  
Arrival Time : 06/05/2025 12:00  
Onsite Hours : 03:00

ASEC Report ID : 82215  
Name of the Project : Rockmart Township - 115 Felton Drive  
Project Location : Rockmart  
Weather : sunny  
Departure Time : 06/05/2025 15:00  
ASEC Technician Name : Sean Willett

| Test Date                                                           | Test Number | Moisture Content (%) | Dry Density (pcf) | Proctor Number | Max. Dry Density (pcf) | Optimum Moisture (%) | Compaction (%) | Specified Compaction (%) | ASTM Test Method | Pass/Fail |
|---------------------------------------------------------------------|-------------|----------------------|-------------------|----------------|------------------------|----------------------|----------------|--------------------------|------------------|-----------|
| 06/05/2025                                                          | 1           | 21.3                 | 97.2              | 2025-012<br>SP | 105.6                  | 18.9                 | 92.0           | 95                       | D2937            | Fail      |
| Location : Lot #133, Elv/Depth :10 feet below finished grade        |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment : Recommended recompaction prior to placement of next lift. |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett                                            |             |                      |                   |                |                        |                      |                |                          |                  |           |

**Remark:** Test performed in general accordance with signed referenced ASTM Method.



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 06/05/2025  
Project No : 2025C160  
Client Company : Artisan  
Arrival Time : 06/05/2025 12:00  
Onsite Hours : 03:00

ASEC Report ID : 82215  
Name of the Project : Rockmart Township - 115 Felton Drive  
Project Location : Rockmart  
Weather : sunny  
Departure Time : 06/05/2025 15:00  
ASEC Technician Name : Sean Willett

---

**PROCTOR DATA SUMMARY**

| TEST DATE  | PROCTOR ID  | MAX DRY DENSITY<br>(pcf) | OPTIMUM MOISTURE<br>(%) | PROCTOR TYPE | SOIL DESCRIPTION           |
|------------|-------------|--------------------------|-------------------------|--------------|----------------------------|
| 03/27/2025 | 2025-008 SP | 115.7                    | 14.7                    | Standard     | Brown Silty SAND with clay |
| 03/27/2025 | 2025-011 SP | 115.0                    | 15.5                    | Standard     | Brown Silty SAND with clay |
| 03/28/2025 | 2025-012 SP | 105.6                    | 18.9                    | Standard     | Brown Sandy CLAY           |