

Date : 07/09/2025
Project No : 2025C160
Client Company : Artisan
Arrival Time : 07/09/2025 08:00
Onsite Hours : 10:00

ASEC Report ID : 82918
Name of the Project : Rockmart Township - 115 Felton Drive
Project Location : Rockmart
Weather : Partly cloudy
Departure Time : 07/09/2025 18:00
ASEC Technician Name : Austin Coleman

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Upon arrival, our representative performed a check plug and moisture test. This was performed on the material delivered from the stockpile on site to be used as a bridge lift. Density testing was later performed for fill placed and compacted.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.