

Date : 08/15/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 08/15/2025 10:30
Onsite Hours : 01:30

ASEC Report ID : 84334
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather :
Departure Time : 08/15/2025 12:00
ASEC Technician Name : Solomon Cherie

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Due to wet site conditions, the grading contractor elected not to perform the placement of fill/backfill this day. Rock drilling (with 3 drills running) continued today for eventual blasting.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Picture depicting project site with current drilling activities

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.