

Date : 09/03/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 09/03/2025 09:30
Onsite Hours : 07:30

ASEC Report ID : 85474
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather : Sunny
Departure Time : 09/03/2025 17:00
ASEC Technician Name : Safiullah Momand

As requested, an ASEC representative visited the project site from 09:30 AM to 06:30 PM to provide quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawings, specifications, applicable codes, and approved material submittals.

The drilling work between Manhole 9A and A10 was in progress by Advance Explosive contractor. Three drilling machines were engaged in the operation. The holes were drilled at approximately 7 ft × 7 ft spacing using a 3.5-inch bit. Depth checks were randomly performed and verified against the drill operator's log sheet.

A total of **48 holes at a depth of 26ft, 10 holes at a depth of 25 ft, and 18 holes at 30 ft** were drilled. The rock was encountered at depths ranging from 0 ft to 9 ft.

The embankment work was ongoing in Lots #8, #9, and #10, at approximate elevations ranging from -2 ft to finish grade. Three nuclear gauge tests were performed in Lots #8, #9, and #10.

We appreciate the opportunity to provide our services on this project, and should there be any questions regarding this report, please feel free to contact us.



Drilling work



Drilling work

Date : 09/03/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 09/03/2025 09:30
Onsite Hours : 07:30

ASEC Report ID : 85474
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather : Sunny
Departure Time : 09/03/2025 17:00
ASEC Technician Name : Safiullah Momand



Drilling work



Drilling work



Drilling work



Embankment work in lots

Date : 09/03/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 09/03/2025 09:30
Onsite Hours : 07:30

ASEC Report ID : 85474
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather : Sunny
Departure Time : 09/03/2025 17:00
ASEC Technician Name : Safiullah Momand




Embankment work in lots



Embankment work in lots



Lots testing



Lots testing

Date : 09/03/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 09/03/2025 09:30
Onsite Hours : 07:30

ASEC Report ID : 85474
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather : Sunny
Departure Time : 09/03/2025 17:00
ASEC Technician Name : Safiullah Momand



Embankment work in lots



Lots testing



Lots testing



driven cylinder tests in lots

Date : 09/03/2025
Project No : 2025C215
Client Company : Artisan
Arrival Time : 09/03/2025 09:30
Onsite Hours : 07:30

ASEC Report ID : 85474
Name of the Project : NW Unit 4 Parkway Ext. Phase 1
Project Location : Dallas
Weather : Sunny
Departure Time : 09/03/2025 17:00
ASEC Technician Name : Safiullah Momand



driven cylinder tests in lots

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.