

Date : 01/02/2026  
Project No : 2025C219  
Client Company : Davidson  
Arrival Time : 01/02/2026 09:00  
Onsite Hours : 00:30

ASEC Report ID : 88936  
Name of the Project : Hickory Bluffs, Retaining Wall  
Project Location : Canton  
Weather : Sunny  
Departure Time : 01/02/2026 09:30  
ASEC Technician Name : Sean Willett

---

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site for the observation/testing of the placement of fill/backfill.

Upon arrival, no contractors were present on site. No testing was performed at this time.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



no contractors present

*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.