

Date : 12/11/2025
Project No : 2025C260
Client Company : Artisan
Arrival Time : 12/11/2025 11:30
Onsite Hours : 04:00

ASEC Report ID : 88468
Name of the Project : NW (PHASE 2) Parkway Extension
Project Location : Dallas
Weather : Sunny
Departure Time : 12/11/2025 15:30
ASEC Technician Name : Clyde Smith

On the above date the writer was on site as requested and observed the grading contractor continue placing rock fill at slope embankment in compacted lifts using a dozer to spread and a sheet foot vibratory roller for compacting. The fill was placed in accordance with recommendations and appeared suitable for compaction requirements .



Undercutting rock fill from Nature Walk Parkway near sanitary sewer manhole #9



Fill placement at slope embankment



Wet conditions at haul road to slope embankment

Date : 12/11/2025
Project No : 2025C260
Client Company : Artisan
Arrival Time : 12/11/2025 11:30
Onsite Hours : 04:00

ASEC Report ID : 88468
Name of the Project : NW (PHASE 2) Parkway Extension
Project Location : Dallas
Weather : Sunny
Departure Time : 12/11/2025 15:30
ASEC Technician Name : Clyde Smith



Fill placement at slope embankment

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.