

Date : 01/09/2026  
Project No : 2025C260  
Client Company : Artisan  
Arrival Time : 01/09/2026 08:00  
Onsite Hours : 04:30

ASEC Report ID : 89046  
Name of the Project : NW (PHASE 2) Parkway Extension  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 01/09/2026 12:30  
ASEC Technician Name : Clyde Smith

---

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site to observe rock drilling at unit 4 phase 2. The Blast contractor didn't show up today. The grading contractor prepared the site for erosion B M P concerns anticipating a rain event. The writer also attended a site meeting to discuss construction procedures and time of planning for construction.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.