

Date : 12/09/2025
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 12/09/2025 07:30
Onsite Hours : 01:00

ASEC Report ID : 88411
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : cloudy
Departure Time : 12/09/2025 08:30
ASEC Technician Name : Clyde Smith

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our representative arrived on site to observe pipe installation which was cancelled due to non-delivery of pipe materials.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.