Daily Field Report

Date : 01/13/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 01/13/2026 07:45
Onsite Hours : 08:45

ASEC Report ID : 89207
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : sunny
Departure Time : 01/13/2026 16:30
ASEC Technician Name : Samara Simha Reddy Kandi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

The crew excavated soils to the required depth and width in accordance with the approved plans. After reaching the design elevation, a layer of gravel bedding was placed at the bottom of the excavation, leveled, and prepared to support the structure and pipe. The precast concrete storm drainage structure was then lowered into position and set on the prepared gravel base. The existing corrugated metal pipe (CMP) was aligned and inserted into the opening of the precast structure. Bricks were installed around the CMP opening to shape and support the connection, and concrete was placed to seal the joint, securing the pipe. Following completion of the structure and pipe connection, backfill material was placed around the structure in 2–3 controlled lifts and compacted using mechanical compaction equipment.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.

Daily Field Report

Date : 01/13/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 01/13/2026 07:45
Onsite Hours : 08:45

ASEC Report ID : 89207
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : sunny
Departure Time : 01/13/2026 16:30
ASEC Technician Name : Samara Simha Reddy Kandi

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.