

Date : 03/05/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 03/05/2026 06:45  
Onsite Hours : 02:15

ASEC Report ID : 91003  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 03/05/2026 09:00  
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (Lewis Grading) and for the observation/testing of the placement of fill/backfill.

ASEC met with Nick (Lewis Grading) to discuss site conditions and requested testing locations. The contractor has been backfilling storm and sewer lines around the site. It appears that the backfill was compacted using a vibrating sheep-foot roller. Density testing was performed and test results were provided to the contractor.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 03/05/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 03/05/2026 06:45  
Onsite Hours : 02:15

ASEC Report ID : 91003  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 03/05/2026 09:00  
ASEC Technician Name : Sean Willett



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.