

Date : 03/23/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 03/23/2026 07:00  
Onsite Hours : 01:00

ASEC Report ID : 91679  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 03/23/2026 08:00  
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (Lewis Contracting) and for the observation/testing of the placement of fill/backfill. The contractor requested density testing around the grease trap structures on site. It appeared that the contractors placed approximately 2 feet of soil and compacted using a sheep-foot roller. Testing was performed and results were provided to the contractor. They have requested ASEC to come back to the site to test the GAB placed in the trenched water lines located on main street.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 03/23/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 03/23/2026 07:00  
Onsite Hours : 01:00

ASEC Report ID : 91679  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 03/23/2026 08:00  
ASEC Technician Name : Sean Willett



*Kenneth Mosman*

**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.