

Date : 03/24/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 03/24/2026 15:00
Onsite Hours : 01:00

ASEC Report ID : 90859
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : Sunny
Departure Time : 03/24/2026 16:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site as requested by the contractor for the observation/testing of the placement of fill/backfill. Upon arrival to the site, our representative spoke with Nick to determine where testing was required. Nick stated that they had been running slower than normal today, and that there was no immediate testing needed. ASEC walked the site to document site progress and left the site. Nick requested another representative to be on site the following day to test backfill.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 03/24/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 03/24/2026 15:00
Onsite Hours : 01:00

ASEC Report ID : 90859
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : Sunny
Departure Time : 03/24/2026 16:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.