

Date : 04/21/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 04/21/2026 13:30
Onsite Hours : 01:30

ASEC Report ID : 93306
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : sunny
Departure Time : 04/21/2026 15:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (Lewis Contracting) and for the observation/testing of the placement of fill/backfill. A proof-roll was performed on the grease trap area located in the middle of the site and the parking area for the town home lots. A loaded tandem-axled truck was used. There were no signs of severe pumping or deflection present in these areas. The contractors are still pouring curbs around the site. It appears the site is almost completed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/21/2026
Project No : 2025C269
Client Company : Lewis Contracting
Arrival Time : 04/21/2026 13:30
Onsite Hours : 01:30

ASEC Report ID : 93306
Name of the Project : Main St. & First Ave. - Mixed-use
Project Location : Lilburn
Weather : sunny
Departure Time : 04/21/2026 15:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.