

Date : 04/23/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 04/23/2026 07:00  
Onsite Hours : 02:00

ASEC Report ID : 93430  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 04/23/2026 09:00  
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor (Lewis Contracting) and for the observation/testing of the placement of fill/backfill. A proof-roll was performed on the roadways and grease trap area located in the middle of the site. A loaded tandem axled truck was used to conduct the proof-roll. Any signs of pumping/deflection were fixed.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 04/23/2026  
Project No : 2025C269  
Client Company : Lewis Contracting  
Arrival Time : 04/23/2026 07:00  
Onsite Hours : 02:00

ASEC Report ID : 93430  
Name of the Project : Main St. & First Ave. - Mixed-use  
Project Location : Lilburn  
Weather : Sunny  
Departure Time : 04/23/2026 09:00  
ASEC Technician Name : Sean Willett

---



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.