

Date : 02/09/2026
Project No : 2025C280
Client Company : WSP
Arrival Time : 02/09/2026 8:00
Onsite Hours : 9:00

ASEC Report ID : 90196
Name of the Project : Lee Road
Project Location : Douglasville
Weather : sunny
Departure Time : 02/09/2026 17:00
ASEC Technician Name : Mahendra Mylabathula

Location(S):

Testing: 1 Set of concrete specimens (6 per set) were cast during the cast-in-place concrete pour at the above referenced location, in accordance with ASTM C31. The specimen will remain on site for the initial 24-48 hrs curing.

Compliance: Field placement of concrete appeared to be in general accordance with the project specifications (i.e., slump, temperature, etc) (refer to remarks below)
 Deviations and/or noncompliances were noted during the field placement (refer to remarks below)

Specimen Pick Up: 1 Sets of concrete specimens/ 6 specimen per set were picked up & transported to AS Engineering and Consulting LLC (ASEC) for curing and testing in accordance with ASTM C39, C670/1231

Field Curing: Specimen were stored for the initial 24 hours
 Near the poured structure
 In an insulated curing box
 Other

Remarks:

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.