

Date : 03/06/2026
Project No : 2026C103
Client Company : Artisan
Arrival Time : 03/06/2026 07:30
Onsite Hours : 07:30

ASEC Report ID : 91089
Name of the Project : NW PH 2, UNIT 4
Project Location : Dallas
Weather : sunny
Departure Time : 03/06/2026 15:00
ASEC Technician Name : Clyde Smith

On the above date the writer was onsite as requested and observed the Pipe contractor continue excavating between manhole # B-4 and B-5 to install 8" pvc sanitary sewer line. Also continued backfilling sanitary sewer line between B-3 and B-5.

The Blast contractor also continued drilling at lots 43 and 42 planning for Blast on 3/9/26.

The Paving contractor also continued placing contract base stone at Nature Walk blvd. between manholes #6 and 9 over recommended repair sub grade areas.



Date : 03/06/2026
Project No : 2026C103
Client Company : Artisan
Arrival Time : 03/06/2026 07:30
Onsite Hours : 07:30

ASEC Report ID : 91089
Name of the Project : NW PH 2, UNIT 4
Project Location : Dallas
Weather : sunny
Departure Time : 03/06/2026 15:00
ASEC Technician Name : Clyde Smith



The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.