

Date : 03/24/2025
Project No : 2025C146
Client Company : Davidson Homes, LLC
Arrival Time : 03/24/2025 9:00
Onsite Hours : 06:00

ASEC Report ID : 80011
Name of the Project : Greene Farms Subdivision
Project Location : 1451 Highway 113, Cartersville, Georgia
Weather : Cloudy
Departure Time : 03/24/2025 15:00
ASEC Technician Name : Aminullah Azimi

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site on this day.

Observed the placement of water lines out of detention pond 1.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Kenneth Mosman

Kenneth Mosman

Date : 03/24/2025
Project No : 2025C146
Client Company : Davidson Homes, LLC
Arrival Time : 03/24/2025 9:00
Onsite Hours : 06:00

ASEC Report ID : 80011
Name of the Project : Greene Farms Subdivision
Project Location : 1451 Highway 113, Cartersville, Georgia
Weather : Cloudy
Departure Time : 03/24/2025 15:00
ASEC Technician Name : Aminullah Azimi

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.